

(defect tracking sheet)

No. _____

PRODUCTION DEFECT CHECK SHEET

Product Line _____ 3G Line _____
 Product Type _____ 3G Alternators _____
 No. of Inspections _____ 280 _____
 Total Number _____ _____
 Lot Number _____ _____

Date _____ 12 / 09 / 02 _____
 Factory _____ Church Street _____
 Data Collector _____ I. M. Quality _____
 Group Name _____ Day Shift _____
 Remarks: _____

TYPE	OCCURRENCE	SUBTOTAL
HIGH TURN ON SPEED		18
HIGH RIPPLE CURRENT		38
HIGH LEAKAGE		12
LOW OUTPUT AT LOW SPEED		15
LOW OUTPUT AT HIGH SPEED		7
DEAD UNIT		4
BAD REGULATOR		22
BAD VOLTAGE SETPOINT		6